



# BLE232PLUS

## DFU Update

**BLE232PLUS DFU Update**

Rev. 0.80.231222

taskit GmbH

## BLE232PLUS

---

All rights to this documentation and to the products described therein are reserved by taskit GmbH.

This document has been prepared with care, nevertheless errors cannot be excluded. Neither the above-mentioned company nor the seller assumes legal liability for errors, resulting operating errors and their consequences. Trademarks, company and product names may be protected by law.

This document may not be reproduced, edited, copied or distributed in whole or in part without written permission. This document was created on 2024-01-16T14:20:43.

## Instruction

This version (0.80.231222) fixes the issue of the connection between BLE232PLUS peripheral and central adapter.

1. The BLE232PLUS adapter must be in the peripheral role.
2. Connect your smartphone to the BLE232PLUS using the "nRF Connect for Mobile" app.
3. Tap on the "DFU" button at the top right.
4. Select "Distribution packet (ZIP)".
5. Find and select the ble232plus\_dfu\_ver0.80.231222.zip.
6. The app tries to upload and update the new firmware. (It often happens that the app loses connection with the adapter. In this case, repeat steps 3 to 6.)
7. Check the firmware version: "Device Information" >> "Firmware Revision String" >> "0.80.231222" or by AT command: ATINFO.